



Wendel
375 Essay Road, Suite 200, Williamsville, NY, 14221
www.wendelcompanies.com
716.688.0766

Road Condition & Vehicle Compliance Report

Date of Report	September 16, 2026
Report #	58
Project Name	Alle-Catt Wind
Location	Town of Freedom
Date of Inspection	September 16, 2026
Time of Inspection	9:00 am
Weather and Temperature (Degrees)	Overcast, Light Rain, 65° (F)
Observer Name	Thomas Miller
Purpose of Visit	To observe and report the conditions of the Town of Freedom jurisdictional roads and infrastructure while in use by the Alle-Catt Wind Project.
Summary of Observations	<ul style="list-style-type: none">- Traveled each Town road known to be used by the project and noted deficiencies observed (see following report pages).- No active roadwork observed during this visit.- Observed culvert crossing near 10379 Osmun Rd per conversation with Town Highway Superintendent. It was relayed to Wendel that this crossing has washed out and been repaired 3 times in the last ~3 weeks. Per Town Highway Superintendent comments, the diversion ditch recently installed upslope of this crossing appears to be aiding in preventing washout. See Osmun Rd photos below for recommendations for further washout (erosion) prevention.- No vehicles seen in violation of the Road Use Agreement when traveling these routes.- See following pages for issues identified on Town roads.

Road / Section Name:	North Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not Satisfactory
Hazards Identified:	<ul style="list-style-type: none"> - North Road is showing deterioration along the East edge of the road - North Road East edge and shoulder near 11509 - North Road is showing lane and edge deterioration South of 11875 - North Road is showing lane deterioration near Bray Road
Maintenance Needed:	<ul style="list-style-type: none"> - Apply QPR to significant potholes - Repair shoulders



East edge of North Road



East edge of North Road



East edge of North Road



North Road East edge and shoulder near 11509



North Road East edge near 11582



North Road North edge and shoulder deterioration near 11614



North Road lane and edge deteriorating with South of 11875



North Road lane, edge, and shoulder deterioration near 11980



Lane deterioration North Rd near intersection with Bray Rd

Road / Section Name:	Eagle Street
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not Satisfactory
Hazards Identified:	<ul style="list-style-type: none"> - Eagle Street is showing signs of deterioration along the West edge of road near intersection with Hughes Road - Eagle Street is showing deterioration along the West edge of the road from 849 to 873 - Eagle Street is showing deterioration along the East side of the road near Bray
Maintenance Needed:	<ul style="list-style-type: none"> - Repair lanes and shoulders.



Eagle Street lane and edge deterioration near 1253



Eagle Street East and West side lane and edge deterioration near 1244



Eagle Street North and South side lane and edge deterioration near 1219



Eagle Street South side lane and edge deterioration near 11405



Eagle Street lane and edge deterioration near 1152



Eagle Street lane and shoulder deterioration near 1111



Eagle Street East edge deterioration near Hughes



Eagle Street lane and East edge deterioration near 994



Eagle Street lane deterioration near 1000



Eagle Street lane and edge deterioration near 931



Eagle Street lane deterioration near 915



Eagle Street lane deterioration South of 849



Eagle Street East edge and shoulder deterioration near 757



Eagle Street lane and edge deterioration North of 757



Eagle Street East lane deterioration near 708

Road / Section Name:	Hughes Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not Satisfactory
Hazards Identified:	- Hughes Road shoulder deterioration on North and South sides East of 951
Maintenance Needed:	- Repair shoulder



Hughes Road edge and shoulder deterioration on North and South sides East of 951

Road / Section Name:	Bray Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not satisfactory
Hazards Identified:	<ul style="list-style-type: none"> - Road edge deterioration progressing into road at intersection of Bray and Eagle.
Maintenance Needed:	<ul style="list-style-type: none"> - Repairs should be made for lane and shoulder deterioration.



Bray Road North edge and shoulder deteriorating from gas pipeline #57 to +/- House 113



Bray Road North edge and shoulder deteriorating from +/-113 to +/-2473



Bray Road South edge and shoulder West of 113



Bray Road North edge and shoulder deteriorating with Pothole near 2407



Bray Road North edge deteriorating near 223



Bray Road South edge and shoulder deteriorating near 223



Bray Road North edge and shoulder deteriorating near 245



Bray Road South edge and shoulder deteriorating near 259



Bray Road North edge and shoulder deteriorating near 2317



Bray Road North edge and shoulder deteriorating near 2231



Bray Road South edge and shoulder deteriorating near 409



Bray Road North edge and shoulder deteriorating from 445 to 475



Bray Road North edge and shoulder deteriorating from 475 to Eagle Street



Bray Road South edge and shoulder deteriorating from 475 to Eagle Street



Bray Road Edge Deterioration at Eagle Street Intersection



Bray Road lane deterioration near intersection with Eagle St



Bray Road North edge and shoulder deteriorating from Eagle Street to +/- 2801



Bray Road South edge and shoulder deteriorating from Eagle Street to +/- 2801



Bray Road North edge and lane deterioration near 2801 (#1)



Bray Road lane deterioration near 2801 (#2)

Road / Section Name:	Brown Schoolhouse Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not satisfactory
Hazards Identified:	<ul style="list-style-type: none"> - Shoulder deteriorating on East and West edge of road - Lane deterioration near Route 98 intersection
Maintenance Needed:	<ul style="list-style-type: none"> - Repair shoulders - Repair intersection



Brown Schoolhouse Road lane deterioration near intersection with Route 98



Brown Schoolhouse Road West shoulder near 11770



Brown Schoolhouse Road East edge and shoulder deterioration from 11754 to 11740



Brown Schoolhouse Road East shoulder deterioration South of 11748



Brown Schoolhouse Road West shoulder North of 11448



Brown Schoolhouse Road East shoulder North of 11448



Brown Schoolhouse Road West shoulder deterioration from 11354 to 11258



Brown Schoolhouse Road West shoulder deterioration from 11214 to 11123

Road / Section Name:	Fisher Blake Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not satisfactory
Hazards Identified:	<ul style="list-style-type: none"> - North edge of road deteriorating near 2195 to +/- 2272 - North edge of road deteriorating near 2177 - North edge of road deteriorating near intersection with Brown Schoolhouse Rd
Maintenance Needed:	<ul style="list-style-type: none"> - Repair shoulders



Fisher Blake Road North edge and shoulder deterioration near intersection with Brown Schoolhouse Road



Fisher Blake Road edge and shoulder deterioration near 2177



Fisher Blake Road North edge and shoulder deterioration near 2195



Fisher Blake Road North edge and shoulder deterioration from 2195 to +/- 2272

Road / Section Name:	Edmunds Road – Invenenergy/Logisticus to confirm whether project is using this road
Initial QES Assessment:	Good
Road Surface Condition:	Not satisfactory
Hazards Identified:	<ul style="list-style-type: none"> - Potholing and lane deterioration forming at intersection with Brown Schoolhouse Rd. This item will be removed from report if confirmed that project does not use this road, see this page for photo. - Edge of road deteriorating near 1812
Maintenance Needed:	<ul style="list-style-type: none"> - Repair intersection - Repair shoulder



Edmunds Road intersection of Brown School House



Edmunds Road South edge and shoulder deterioration 1940 to 1850



Edmunds Rd Southeast edge and shoulder deteriorating near 1812



Edmunds Rd lane and shoulder deterioration on North and South sides of Rd near intersection with Maple Grove

Road / Section Name:	Strong Road – Currently not in RUA but being used by project
Initial QES Assessment:	Poor
Road Surface Condition:	Poor
Hazards Identified:	- Multiple potholes in paved sections of road
Maintenance Needed:	- Apply QPR to significant potholes
Non-Hazard Items for Continued Observation:	- Unpaved sections have been filled with gravel.



Strong Road potholes



Strong Rd potholes



Strong Road pothole

Road / Section Name:	Siloam Road
Initial QES Assessment:	Poor
Road Surface Condition:	Satisfactory
Hazards Identified:	- Lane and edge deterioration from Maple Grove to Blue Street (REPAIRED)
Maintenance Needed:	-
Non-Hazard Items for Continued Observation:	-



Siloam Road lane deterioration near intersection with Maple Grove (REPAIRED)



Siloam Road South shoulder deterioration near 1675 (REPAIRED)



Siloam Road North and South shoulder deterioration from +/- 1675 to +/- 1579 (REPAIRED)

Road / Section Name:	Galen Hill Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not satisfactory
Hazards Identified:	<ul style="list-style-type: none"> - Galen Hill Rd and 98 intersection pothole - Lane deterioration from Phillippi Rd to 10553 Gallen Hill
Maintenance Needed:	<ul style="list-style-type: none"> - Large pothole and deterioration at Galen Hill Rd and 98 intersection, repairs needed. - Repair lane from Phillippi Rd to 10553 Galen Hill
Non-Hazard Items for Continued Observation:	<ul style="list-style-type: none"> - Minor deterioration throughout lanes of travel to be monitored, see this page.



Galen Hill Road intersection with Phillippi Rd lane deterioration



Galen Hill Road lane deterioration from Phillippi Rd to 10553



Galen Hill Rd pothole at intersection of Route 98



Galen Hill West edge and shoulder deterioration North of 10075

Road / Section Name:	Sandbank Road
Initial QES Assessment:	Fair
Road Surface Condition:	Not satisfactory
Hazards Identified:	- Road surface deterioration near 10317
Maintenance Needed:	- Discuss repair with Highway Supervisor
Non-Hazard Items for Continued Observation:	- Road edge deterioration, Road surface deterioration



Sandbank Road East edge and shoulder deterioration near 9999



Sandbank Rd East and West edge deterioration North and South of 10157 to +/- 10220



Sandbank Road East and West edge / shoulder deterioration near 10238



Sandbank Rd West lane and edge deterioration South of 10317



Sandbank Rd East lane and edge deterioration South of 10317



Sandbank Rd lane deterioration near 10317



Sandbank Road East edge deterioration South of 10368



Sandbank Rd East and West side shoulder deterioration near 10442



Sandbank Road (East and West) edge and shoulder deteriorating near intersection with Cross Road

Road / Section Name:	Osmun Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not satisfactory
Hazards Identified:	<ul style="list-style-type: none"> - Road edge deterioration next to 10220 Osmun Rd. - Road edge and lane deterioration near Zimmer Rd, see this page for photo. - Curvert/road washout condition near 10379 Osmun Rd.
Maintenance Needed:	<ul style="list-style-type: none"> - Apply QPR to significant potholes. - Repair shoulder - Maintain diversion ditch and install additional erosion control measures near 10379 Osmun (see photos)
Non-Hazard Items for Continued Observation:	<ul style="list-style-type: none"> - Monitor repairs made to road edges



Osmun Rd Edge and shoulder deterioration near Zimmer



Osmun Rd lane deterioration near Zimmer



Osmun Road lane deterioration South of 10200



Osmun Road East lane and shoulder deterioration near 10200



Osmun Rd lane deterioration North of 10220 near construction entrance



Osmun Rd: Ditch to divert water into Culvert near 10379. According to Town Highway Superintendent, the diversion ditch is helping prevent erosion. Ditch to be maintained as needed.



Osmun Rd: Ditch to divert water into Culvert near 10379. According to Town Highway Superintendent, the diversion ditch is helping prevent erosion. Ditch to be maintained as needed.



Osmun Rd: East end of 5' Dia. HDPE Culvert under Osmun Rd near 10379



Osmun Rd: East side of 5' Dia. HDPE Culvert near 10379 facing East



Osmun Rd: West side of Culvert near 10379. Exposed side slope subject to washout.



Osmun Rd: West end of Culvert near 10379. Recommend cutting pipe back to daylight grade and installing rock outlet protection to prevent further erosion of outlet area.



Osmun Rd: West end of Culvert near 10379. Consider rock revetment (rock lining) alongside slope from the road to prevent further washout of this slope.



Osmun Rd: West side of Culvert near 10379 facing West



Osmun Rd: Road over Culvert near 10379 facing North



Osmun Rd: Road over Culvert near 10379 facing South. Road edge deterioration is evident.



Osmun Rd: Construction Entrance nearest to Culvert @ 10379 facing East



Osmun Rd East side lane, edge, and shoulder deterioration North and South of 10410



Osmun Road East edge and shoulder deterioration near 10571



Osmun Rd edge deterioration South of 10674



Osmun Road lane deterioration near 10674

Road / Section Name:	Baird Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not satisfactory
Hazards Identified:	- Deterioration of shoulder (both sides of Rd)
Maintenance Needed:	- Repair shoulder



Baird Rd South shoulder deterioration East and West of 379



Baird Rd North shoulder deterioration East and West of 379



Baird Road South edge deterioration from +/- 379 to +/- 253



Baird Road North edge deterioration from +/- 379 to +/- 253



Baird Road lane deterioration from 253 to 187

Road / Section Name:	Jones Road – Currently not in RUA but being used by project
Initial QES Assessment:	Fair
Road Surface Condition:	- Not satisfactory
Hazards Identified:	N/A
Maintenance Needed:	- Repair this spring.
Non-Hazard Items for Continued Observation:	- Jones Rd. should be paved from Route 98 to the bridge, see this page for photo.



Jones Rd



Jones Rd bridge

Vehicle Compliance Check

Road / Section Name:	N/A
Designation Type:	
Vehicles Observed:	
Compliance Status:	
Notes:	No vehicles seen in violation of the Road Use Agreement.

Roads Observed

- Baird Road
- Blue Street
- Bray Road
- Brown Schoolhouse Road
- B&S Road
- Cheeseman Hill Road
- Cross Road
- Eagle Street
- Edmunds Road
- Fisher Blake Road
- Galen Hill Road
- Hughes Road
- Jones Road
- North Road
- Osmun Road
- Pigeon Hill Road
- Sandbank Road
- Siloam Road
- Sparks Road
- Strong Road
- Witt Road
- Zimmer Road