



Wendel
375 Essjay Road, Suite 200, Williamsville, NY, 14221
www.wendelcompanies.com
716.688.0766

Road Condition & Vehicle Compliance Report

Date of Report	October 07, 2026
Report #	60
Project Name	Alle-Catt Wind
Location	Town of Freedom
Date of Inspection	October 07, 2026
Time of Inspection	9:00 am
Weather and Temperature (Degrees)	Sun, 55° (F)
Observer Name	Thomas Miller
Purpose of Visit	To observe and report the conditions of the Town of Freedom jurisdictional roads and infrastructure while in use by the Alle-Catt Wind Project.
Summary of Observations	<ul style="list-style-type: none">- Traveled each Town road known to be used by the project and noted deficiencies observed (see following report pages).- Active roadwork was observed during this visit.- No vehicles seen in violation of the Road Use Agreement when traveling these routes.- See following pages for issues identified on Town roads.

Road / Section Name:		North Road
Initial QES Assessment:		Satisfactory
Road Surface Condition:		Satisfactory
Hazards Identified:		-
Maintenance Needed:		-



East edge of North Road (REPAIRED)



East edge of North Road (REPAIRED)



East edge of North Road (REPAIRED)



North Road East edge and shoulder near 11509 (REPAIRED)



North Road East edge near 11582 (REPAIRED)



North Road North edge and shoulder near 11614 (REPAIRED)



North Road lane and edge South of 11875 (REPAIRED)



North Road lane, edge, and shoulder near 11980 (REPAIRED)



North Rd near intersection with Bray Rd (REPAIRED)

Road / Section Name:	Eagle Street
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not Satisfactory
Non-Hazards Identified:	- Eagle Street lane deficiency near 915
Maintenance Needed:	- Repair lane



Eagle Street lane and edge near 1253 (REPAIRED)



Eagle Street East and West side lane and edge near 1244 (REPAIRED)



Eagle Street North and South side lane and edge near 1219 (REPAIRED)




Eagle Street South side lane and edge near 11405 (REPAIRED)



Eagle Street lane and edge near 1152 (REPAIRED)



Eagle Street lane and shoulder near 1111 (REPAIRED)



Eagle Street East edge near Hughes (REPAIRED)



Eagle Street lane and East edge near 994 (REPAIRED)



Eagle Street lane near 1000 (REPAIRED)



Eagle Street lane and edge near 931 (REPAIRED)



Eagle Street lane near 915



Eagle Street lane South of 849 (REPAIRED)



Eagle Street East edge and shoulder near 757 (REPAIRED)



Eagle Street lane and edge North of 757 (REPAIRED)



Eagle Street East lane near 708 (REPAIRED)

Road / Section Name:	Hughes Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Satisfactory
Hazards Identified:	-
Maintenance Needed:	-



Hughes Road edge and shoulder on North and South sides East of 951 (REPAIRED)

Road / Section Name:	Bray Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not satisfactory
Hazards Identified:	<ul style="list-style-type: none"> - Edge/shoulder deficiency at various locations.
Maintenance Needed:	<ul style="list-style-type: none"> - Repairs should be made to lane and shoulder.



Bray Road North edge and shoulder from gas pipeline #57 to +/- House 113



Bray Road North edge and shoulder from +/-113 to +/-2473



Bray Road South edge and shoulder West of 113



Bray Road North edge and shoulder near 2407



Bray Road North edge near 223



Bray Road South edge and shoulder near 223 (REPAIRED)



Bray Road North edge and shoulder near 245 (REPAIRED)



Bray Road South edge and shoulder near 259



Bray Road North and South edge and shoulder near 2317



Bray Road North edge and shoulder near 2231



Bray Road South edge and shoulder near 409



Bray Road North edge and shoulder from 409 to 475 (REPAIRED)



Bray Road South edge and shoulder from 475 to Eagle Street (REPAIRED)



Bray Road North edge West of Hiram (REPAIRED)



Bray Road North side from Hiram to +/- Eagle Street – No Shoulder



Bray Road Edge at Eagle Street Intersection (REPAIRED)



Bray Road lane near intersection with Eagle St (REPAIRED)



Bray Road North edge and shoulder from Eagle Street to +/- 2801 (REPAIRED)



Bray Road South edge and shoulder from Eagle Street to +/- 2801 (REPAIRED)



Bray Road North edge and lane near 2801 (#1) (REPAIRED)



Bray Road lane near 2801 (#2) (REPAIRED)

Road / Section Name:	Brown Schoolhouse Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not satisfactory
Hazards Identified:	- Shoulder deficiencies on East and West edge of road
Maintenance Needed:	- Repair shoulders



Brown Schoolhouse Road lane near intersection with Route 98 (REPAIRED)



Brown Schoolhouse Road West shoulder near 11770



Brown Schoolhouse Road East shoulder South of 11748 (REPAIRED)



Brown Schoolhouse Road West shoulder North of 11448



Brown Schoolhouse Road East shoulder North of 11448




Brown Schoolhouse Road West shoulder from 11354 to 11258



Brown Schoolhouse Road West shoulder from 11214 to 11123 (REPAIRED)

Road / Section Name:	Fisher Blake Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Satisfactory
Hazards Identified:	-
Maintenance Needed:	-



Fisher Blake Road North edge and shoulder near intersection with Brown Schoolhouse Road
(REPAIRED)



Fisher Blake Road edge and shoulder near 2177 (REPAIRED)



Fisher Blake Road North edge and shoulder near 2195 (REPAIRED)



Fisher Blake Road North edge and shoulder from 2195 to +/- 2272 (REPAIRED)

Road / Section Name:	Edmunds Road – Town confirmed project is using this road
Initial QES Assessment:	Good
Road Surface Condition:	Not Satisfactory
Hazards Identified:	- Road edge deficiency near 1812
Maintenance Needed:	- Repair intersection - Repair shoulder



Edmunds Road intersection of Brown School House (REPAIRED)



Edmunds Road South edge and shoulder 1940 to 1850



Edmunds Rd Southeast edge and shoulder near 1812



Edmunds Rd lane and shoulder on North and South sides of road near intersection with
Maple Grove

Road / Section Name:	Strong Road – Currently not in RUA but being used by project
Initial QES Assessment:	Poor
Road Surface Condition:	Poor
Hazards Identified:	- Multiple deficiencies in paved sections of road
Maintenance Needed:	- Repair deficiencies
Non-Hazard Items for Continued Observation:	- Unpaved sections have been filled with gravel.



Strong Road deficiencies



Strong Rd deficiencies



Strong Road deficiencies

Road / Section Name:	Galen Hill Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not Satisfactory
Hazards Identified:	<ul style="list-style-type: none"> - Galen Hill Rd and 98 intersection deficiency - Lane deficiency from Phillippi Rd to 10553 Gallen Hill
Maintenance Needed:	<ul style="list-style-type: none"> - Deficiency at Galen Hill Rd and 98 intersection, repairs needed. - Repair lane from Phillippi Rd to 10553 Galen Hill
Non-Hazard Items for Continued Observation:	<ul style="list-style-type: none"> - Minor deficiencies throughout lanes of travel to be monitored, see this page.



Galen Hill Road intersection with Phillippi Rd lane



Galen Hill Road lane from Phillippi Rd to 10553



Galen Hill Rd at intersection of Route 98



Galen Hill Rd pavement repair between construction entrances (REPAIRED)



Galen Hill West edge and shoulder North of 10075

Road / Section Name:	Sandbank Road
Initial QES Assessment:	Fair
Road Surface Condition:	Not Satisfactory
Hazards Identified:	- Lane and edge deficiencies (see photos)
Maintenance Needed:	- Repair lane and edge
Non-Hazard Items for Continued Observation:	-



Sandbank Road East edge and shoulder near 9999



Sandbank Rd East and West edge North and South of 10157 to +/- 10220



Sandbank Road East and West edge / shoulder near 10238



Sandbank Rd West lane and edge South of 10317



Sandbank Rd East lane and edge South of 10317



Sandbank Rd lane near 10317



Sandbank Road East edge South of 10368



Sandbank Rd East and West side shoulder near 10442



Sandbank Road (East and West) edge and shoulder near intersection with Cross Road

Road / Section Name:	Osmun Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not Satisfactory
Hazards Identified:	<ul style="list-style-type: none"> - Lane/edge/shoulder deficiency near 10410
Maintenance Needed:	<ul style="list-style-type: none"> - Maintain diversion ditch and install additional erosion control measures near 10379 Osmun
Non-Hazard Items for Continued Observation:	<ul style="list-style-type: none"> - Monitor repairs made to road edges



Osmun Rd: Road over Culvert near 10379 facing North (REPAIRED)



Osmun Rd East side lane, edge, and shoulder North and South of 10410

Road / Section Name:	Baird Road
Initial QES Assessment:	Satisfactory
Road Surface Condition:	Not Satisfactory
Hazards Identified:	<ul style="list-style-type: none"> - Shoulder South edge from +/- 379 to +/- 253 - Lane from +/-253 to +/-187
Maintenance Needed:	<ul style="list-style-type: none"> - Repair shoulder and lane



Baird Road South edge from +/- 379 to +/- 253



Baird Road lane from +/-253 to +/-187

Road / Section Name:	Jones Road – Currently not in RUA but being used by project
Initial QES Assessment:	Fair
Road Surface Condition:	Not Satisfactory
Hazards Identified:	N/A
Maintenance Needed:	-
Non-Hazard Items for Continued Observation:	- Jones Rd. should be paved from Route 98 to the bridge



Jones Rd



Jones Rd bridge

Vehicle Compliance Check

Road / Section Name:	N/A
Designation Type:	
Vehicles Observed:	
Compliance Status:	
Notes:	No vehicles seen in violation of the Road Use Agreement.

Roads Observed

- Baird Road
- Blue Street
- Bray Road
- Brown Schoolhouse Road
- B&S Road
- Cheeseman Hill Road
- Cross Road
- Eagle Street
- Edmunds Road
- Fisher Blake Road
- Galen Hill Road
- Hughes Road
- Jones Road
- North Road
- Osmun Road
- Pigeon Hill Road
- Sandbank Road
- Siloam Road
- Sparks Road
- Strong Road
- Witt Road
- Zimmer Road